



Advisory



ATCSCC Advisory

ATCSCC ADVZY 022 BOS/ZBW 10/31/2000 CDM GROUND DELAY PROGRAM

MESSAGE: AIRPORT: BOS
 ADL TIME: 11:26Z
 PROGRAM TYPE: RBS PP
 ARRIVALS ESTIMATED FOR: 311200Z - 311959Z
 PROGRAM AAR: 30
 ALL CENTERS ARE INCLUDED IN THE PROGRAM. THE FOLLOWING SHALL APPLY
 FA DELAYS:
 (Manual) ZAU ZBW ZDC ZFW ZHU ZID ZJX ZKC ZMA ZME ZMP ZNY ZOB ZTL
 CYUL CYHZ CYYZ CYOW
 EXEMPTED AIRPORTS: NONE
 MAXIMUM DELAY: 279
 AVERAGE DELAY: 149
 REASON: OTHER, WIND/SINGLE RWY OPS
 REMARKS: TAXIWAY CONSTRUCTION AND WIND FORCING A SINGLE RWY (4R) FOR
 ARRIVALS
 AND DEPARTURES.

EFFECTIVE TIME: 311133 - 312059

SIGNATURE: 00/10/31 11:34 FSA.//wkstn15 703-708-5115

< Back to Results

<< Back to Search Form

<<< Back to Most Recent Advisory

[[Advisories](#)] [[ATCSCC Logs](#)] [[AADC](#)] [[Weather](#)] [[NASSI](#)] [[Opsnet](#)]

05T-00-8164-14



ATCSCC Advisory

ATCSCC ADVZY 030 IAH/ZHU 10/31/2000 IAH ARRIVAL DELAYS

MESSAGE: USERS CAN EXPECT ARRIVAL DELAYS INTO THE IAH AIRPORT OF BETWEEN 30-45 MINUTES DUE TO FOG AND COMPACTED DEMAND. USERS CAN EXPECT HOLDING FROM 1400-1500Z UNLESS IMPROVEMENT IN THE WX IS REALIZED. UPDATES WILL FOLLOW AS NECESSARY.

EFFECTIVE TIME: 301212 - 301459

SIGNATURE: 00/10/31 12:13 FSB./wkstn19 703-708-5119

[< Back to Results](#)

[<< Back to Search Form](#)

[<<< Back to Most Recent Advisory](#)

[\[Advisories\]](#) [\[ATCSCC Logs\]](#) [\[AADC\]](#) [\[Weather\]](#) [\[NASSI\]](#) [\[Opsnet\]](#)

**ATCSCC Advisory****ATCSCC ADVZY 035 IAH/ZHU 10/31/2000 CDM GROUND STOP**

MESSAGE: AIRPORT: IAH
ADL TIME: 13:01Z
GROUND STOP PERIOD: 1251Z - 1415Z
FACILITIES INCLUDED: (Manual) ZAB ZFW ZHU ZTL
PREVIOUS TOTAL, MAXIMUM, AVERAGE DELAYS: 0/ 0/ 0.00
NEW TOTAL, MAXIMUM, AVERAGE DELAYS: 1066/ 79/ 41.0
REASON: WEATHER, FOG
REMARKS: EXPECT UPDATE: 1415Z USERS CAN EXPECT AIRBORNE HOLDING OF
UP TO 60
MINS.

EFFECTIVE TIME: 311306 - 311459

SIGNATURE: 00/10/31 13:07 FSB.//wkstn19 703-708-5119

[< Back to Results](#)[<< Back to Search Form](#)[<<< Back to Most Recent Advisory](#)

[\[Advisories\]](#) [\[ATCSCC Logs\]](#) [\[AADC\]](#) [\[Weather\]](#) [\[NASSI\]](#) [\[Opsnet\]](#)



ATCSCC Advisory

Anomalies were encountered while converting this advisory. The original raw text is shown in the table labeled 'Original Advisory' below.

ATCSCC ADVZY 080 ZID 10/31/2000 POSSIBLE POWER FAILURE

MESSAGE:

ATCSCC HAS BEEN INFORMED THAT A FAILURE HAS OCCURED AT ZID. THE EXTENT OF THE LOST EQUIPMENT IS NOT KNOWN AT THIS TIME HOWEVER IT IS BELIEVED THAT RADAR SERVICES HAVE BEEN EXTENSIVELY CURTAILED. UNTIL SUCH TIME THAT ADDITIONAL INFORMATION IS AVAILABLE ALL FIRST TIER CENTERS TO ZID HAVE BEEN INSTRUCTED TO IMPLEMENT A GROUND STOP TO ALL AIRCRAFT DESTINED TO AIRPORTS WITHIN ZID AND TO ALL FLIGHTS THAT ARE FLIGHT PLANNED TO TRANSIT ZID AIRSPACE.

ALL CENTERS ARE REQUESTED TO PARTICIPATE IN A TELCON AT 2130Z. INTERESTED USERS ARE ENCOURAGED TO ALSO PARTICIPATE. FACILITIES AND USERS SHOULD USE THE NORMAL SPT TELCON NUMBER AND PIN NUMBERS.

EFFECTIVE TIME: 312125 - 312140

SIGNATURE: 00/10/31 21:26 FSB.//wkstn05a 703-708-5146

Original Advisory

RAW TEXT: ATCSCC ADVZY 080 ZID POSSIBLE POWER FAILURE 10-31-00

ATCSCC HAS BEEN INFORMED THAT A FAILURE HAS OCCURED AT ZID. THE EXTENT OF THE LOST EQUIPMENT IS NOT KNOWN AT THIS TIME HOWEVER IT IS BELIEVED THAT RADAR SERVICES HAVE BEEN EXTENSIVELY CURTAILED. UNTIL SUCH TIME THAT ADDITIONAL INFORMATION IS AVAILABLE ALL FIRST TIER CENTERS TO ZID HAVE BEEN INSTRUCTED TO IMPLEMENT A GROUND STOP TO ALL AIRCRAFT DESTINED TO AIRPORTS WITHIN ZID AND TO ALL FLIGHTS THAT